

Transportation Committee report, June 2016

The concrete barriers have been removed from the section of Moore Hill road which has slumped. A geologist has examined the area and concluded that there is unlikely to be further subsidence of the road, therefore the plan is to resurface the road to bring it back to level and to seal it against further water ingress. This will be accomplished this summer. Highways will continue to monitor for any signs of renewed slumping.

Submitted by:

Graeme Shelford

Chair, Transportation Committee